

ST NICHOLAS CHURCH, RADFORD SEMELE

Brief Description

On 16th March 2008, St Nicholas Church was devastated by fire, leaving only the shell and the tower intact. A major refurbishment project was put in place and after five years, the church reopened on 16th May 2013.

Facilities, including a kitchen and office, have been put in place to allow the church to be used for the wider community.

Project Details

Location: Radford Semele, Warwickshire
Client: PCC of St Nicholas Church
Value: £1.5 million
Dates: 2010-2013



Professional Services

Martin Thomas Associates were appointed to undertake all the Mechanical and Electrical Consultancy Work.

Services Include

- Power supply
- Distribution
- Internal and external lighting
- Fire alarm and detection
- Security installation
- Communication systems
- Comfort heating system
- Hot & Cold water services
- Water supply
- Gas supply
- Kitchen services
- Mechanical ventilation